



VEHICLE INSPECTION REPORT

GU22VVA

Ford Kuga 2.5 PHEV ST-Line Edition 5dr CVT

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	11/03/2022	Body Style	Hatchback	Last service miles	12,585
Year	2022	Keys	1	MOT Due	20/04/2027
Mileage	12,754 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Printout	Gears	1
Colour	BLACK	Number of stamps	4	Doors	5
VIN	WF0FXXWPMHNL46225	Last service date	21/04/2026		

Last service 21/04/2026 at 12,585 miles- 4 main dealer services Type 2 and 3 pin charging cables in boot

Tyres



NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsr
Chipped
1 To 5



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Door osf
Chipped
1 To 5



10: Door Moulding osf
Scratched (Painted)
UpTo 25mm Thru Paint



11: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



12: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK