



VEHICLE INSPECTION REPORT

GV19KYU

Toyota Yaris 1.5 Hybrid Y20 5dr CVT [Bi-tone]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	21/05/2019	Keys	2	CAP Average	£8,725.00
Year	2019	Service history	Yes	CAP Below	£7,725.00
Mileage	44,971 Miles Warranted	Number of stamps	2	Gearbox	CVT
Fuel Type	Hybrid Electric	Last service date	16/09/2022	Gears	1
Colour	WHITE/BLACK	Last service miles	14,525	Doors	5
VIN	VNKKD3D320A592327	MOT Due	Expired		
Body Style	Hatchback	CAP Clean	£9,800.00		

MOT Expired Boot heavily stained

Tyres


NSF	BUDGET	OK
NSR	BUDGET	Worn
OSF	BUDGET	2.0mm
OSR	DAVANTI	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Park assist camera
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Dented
Over 30mm



7: Qtr Panel nsr
Dented
Over 30mm



8: Wheel nsr
Scratched
Over 50mm




9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Boot Lid
Scratched
Over 25mm Not Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Scratched
Over 25mm Not Thru Paint




13: Door osf
Scratched
Over 25mm Not Thru Paint




14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Dented
With Paint Damage



16: Tyre nsr
Worn
Replace



17: Tyre nsr
Worn
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK