



VEHICLE INSPECTION REPORT

GV24NXL

Peugeot 208 1.2 PureTech 100 Allure 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	25/07/2024	Body Style	Hatchback	Last service miles	12,357
Year	2024	Keys	2	Gearbox	MANUAL
Mileage	20,658 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Petrol	Service documents	Printout	Doors	5
Colour	BLACK	Number of stamps	1		
VIN	VR3UPHNE7R4192246	Last service date	14/07/2025		

£90 ADDITIONAL FEE

Last service 14/07/2025 at 12,357 miles- 1 service. Print

Tyres

NSF	NEXEN	5.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	2.0mm
OSR	BUDGET	5.0mm


Spare

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check




Damage Photos




1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wing nsf
Dented
With Paint Damage




4: Wheel nsf
Scratched
Over 50mm




5: Door nsf
Scratched
Over 25mm Thru Paint




6: Door osr
Chipped
1 To 5




7: Wheel nsr
Scratched
Over 50mm




8: Qtr Panel nsr
Poor Previous Repair
Poor Paint




9: Bumper Rear
Poor Previous Repair
Poor Paint




10: Qtr Panel osr
Poor Previous Repair
Poor Paint




11: Wheel osr
Scratched
Over 50mm




12: Door osr
Poor Previous Repair
Rippled UpTo 30%



13: Door osf
Chipped
Edge Chip



14: Wheel osf
Scratched
Over 50mm



15: Wing of
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK