



# VEHICLE INSPECTION REPORT

**YT11TBZ**

## Land Rover Freelander 2.2 SD4 XS 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	16/03/2011	Body Style	Estate	Last service miles	85,047
Year	2011	Keys	1	MOT Due	08/04/2026
Mileage	143,320 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	7		
VIN	SALFA2AE2BH246767	Last service date	01/04/2017		

£65 ADDITIONAL FEE.

Last Service - 01.04.2017 at 85047 miles (7 services)

Intermittent rough idle

Knocking from N/S/F

### Tyres


NSF	LAUFENN	4.0mm
NSR	LAUFENN	4.0mm
OSF	LAUFENN	4.0mm
OSR	LAUFENN	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- PAS
- Audio remote control
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Radio/CD
- Climate control
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
Over 100mm Thru Paint



2: Wheel osr  
Scratched  
Over 50mm






3: Qtr Panel osr  
Dented  
With Paint Damage



4: Door osr  
Chipped  
1 To 5



5: Door osr  
Scratched  
Over 25mm Not Thru Paint



6: Door osf  
Chipped  
Multiple Chips



7: Wing osf  
Scratched  
Over 25mm Thru Paint



8: Wheel osf  
Scratched  
Over 50mm



9: Bumper Front  
Chipped  
Multiple Chips

No Image

10: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



11: Bonnet  
Chipped  
1 To 5



12: Wheel nsf  
Corroded  
Light



13: Other  
N/A  
N/A

No Image

14: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



15: Door nsf  
Chipped  
1 To 5



16: Door nsr  
Scratched  
Over 25mm Not Thru Paint




17: Wheel nsr  
Corroded  
Light



18: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



19: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



20: Qtr Panel nsr  
Dented  
Hail - Severe

## Interior



**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK