



VEHICLE INSPECTION REPORT

GF64UDY

Ford Fiesta 1.0 EcoBoost Titanium 5dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	10/11/2014	Body Style	Hatchback	Last service miles	82,205
Year	2014	Keys	2	MOT Due	09/11/2026
Mileage	104,419 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	8	Doors	5
VIN	WF0DXXGAKDEP59654	Last service date	27/10/2023		

LAST SERVICE 27/10/2023 @ 82,205 MILES (8 SERVICES, 6 MAIN DEALER) Engine noisy
 Exhaust blowing
 Tyres sensors not detected message displayed

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	SUNNY	2.0mm
OSR	BUDGET	5.0mm


Spare

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Door osr
Dented
Over 30mm



12: Roof
Scratched
UpTo 25mm Thru Paint



13: Door osf
Scratched
Over 25mm Thru Paint



14: Wing osf
Scratched
Over 25mm Thru Paint



15: Screen Front
Cracked
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK