

# **VEHICLE INSPECTION REPORT**

**GU18MWX** 

# Ford Fiesta 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape.
		V5	Present		
Details					
Reg. date	10/04/2018	Keys	2	CAP Clean	£4,125.00
Year	2018	Service history	Yes	CAP Average	£3,525.00
Mileage	100,386 Miles Warranted	Service documents	Printout	CAP Below	£2,975.00
		Number of stamps	1	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	02/01/2025	Gears	6
Colour	BLACK	Last service miles	93,611	Doors	 5
VIN	WF0JXXGAHJJY88296		09/04/2026		<u>-</u>
Body Style	Hatchback		30,0 ., 2020		

### £100 ADDITIONAL FEE Last service 02/01/2025 @ 93611 miles (5 SERVICES 1 MAIN DEALER) book + print Gear linkage is floppy

Tyres			
NSF	BUDGET	4.0mm	
NSR	BUDGET	4.0mm	
OSF	BUDGET	5.0mm	
OSR	BUDGET	5.0mm	
Spare			

### **Features**

- Bluetooth connection
- Radio/CD
- · Front electric windows
- Drivers airbag
- · Remote central locking
- Navigation system
- Body coloured bumpers
- Rear headrests
- Traction control
- · Cloth seat trim
- Rear wiper
- · Electric door mirrors
- Metallic Paint
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Central locking

#### **Photos**












# **Condition Check**



# **Damage Photos**




1: Carpets Front Holed Over 3mm



2: Wheel osf Scratched Over 50mm



3: Wing osf Chipped 1 To 5



4: Door osf Dented With Paint Damage



5: Qtr Panel osr Scratched Over 25mm Not Thru Paint



6: Bumper Rear Chipped 1 To 5



7: Qtr Panel nsr Scratched Over 25mm Not Thru Paint




8: Wheel nsr Scratched Over 50mm



9: Door nsr Scratched Over 25mm Not Thru Paint



10: Door nsf Chipped Edge Chip



11: Door nsf Chipped 1 To 5




12: Wing nsf Scratched Over 25mm Not Thru Paint




13: Wheel nsf Scratched Over 50mm



14: Bumper Front Scratched 25 to 100mm Thru Paint



15: Bumper Front Scratched Over 25mm Not Thru Paint



16: Bonnet Scratched Over 25mm Not Thru Paint

#### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

## **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK	J	
-			
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK