

46 Brampton Road Eastbourne BN22 9BN 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



Jaguar XF 2.0d [180] R-Sport 4dr Auto AWD

| Inspection | | Vehicle | | | nama |
|-----------------|----------------------------|--------------------|------------|-------------|-----------|
| Serious Damage? | No | VAT | Margin | | S SAPE |
| | | V5 | Present | | |
| Details | | | | | |
| Reg. date | 07/10/2016 | Keys | 2 | CAP Average | £4,250.00 |
| Year | 2016 | Service history | Yes | CAP Below | £3,700.00 |
| Mileage | 103,894 Miles Warranted | Service documents | Printout | Gearbox | AUTOMATIC |
| | | Last service date | 15/10/2024 | Gears | 8 |
| Fuel Type | Diesel | Last service miles | 96,896 | Doors | 4 |
| Colour | BLUE | MOT Due | 25/10/2025 | | |
| VIN | SAJBA4AN4HCY36493 | | £4,775.00 | | |
| Body Style | Saloon | | | | |

£100 ADDITIONAL FEE Last service 15/10/2024 @ 96896 miles (3 SERVICES 1 MAIN DEALER) Slight engine knock

| Tyres | | | |
|-------|----------|-------|--|
| NSF | BUDGET | 2.0mm | |
| NSR | AUTOGRIP | 3.0mm | |
| OSF | BUDGET | 4.0mm | |
| OSR | AUTOGRIP | 4.0mm | |
| Spare | | | |

Features

- Bluetooth connection
- Navigation system
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear headrests
 - Passenger airbag
- Remote central locking
- Heated front seat
- Radio/CD
- Climate control
- Metallic Paint
 Traction control
- Traction controlLeather seat trim


Photos







Condition Check



Damage Photos



1: Wheel osf Scratched Over 50mm

2: Wing osf Chipped 1 To 5





3: Door osf Chipped 1 To 5







5: Door osr Chipped 1 To 5



7: Bumper Rear Scratched Over 25mm Not Thru Paint

6: Wheel osr Scratched Over 50mm



8: Tailgate Chipped 1 To 5



9: Tailgate Dented 2 Or Less UpTo 10mm



11: Wheel nsr Scratched Over 50mm



10: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



12: Door nsr Scratched Over 25mm Not Thru Paint



13: Door nsf Scratched Over 25mm Not Thru Paint




14: Wing nsf Scratched UpTo 25mm Thru Paint





15: Wing nsf Scratched Over 25mm Not Thru Paint

16: Wheel nsf Scratched Over 50mm



17: Bumper Front Poor Previous Repair Paint Flake

Interior

| Carpet Condition | |
|------------------|--|
| Seat Condition | |

Average Average Upholstery Condition Odour Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

| Engine Runs OK | Gearbox 1st and Reverse Test OK |
|-------------------|---|
| Brakes OK | Clutch Slip Test from Static OK |
| Turbo Boosting OK | Gearbox Static Gear Selection (engine running) OK |
| Parking Brake OK | No Excessive Smoking OK |



18: Bonnet Poor Previous Repair Paint Flake

Eastbourne Car Auctions

| EML light illuminated OK | | Oil warning light illuminated | ОК |
|--------------------------|----|-------------------------------------|----|
| Airbag light illuminated | | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |