



# VEHICLE INSPECTION REPORT

**DK67OHD**

## Ford Kuga 1.5 EcoBoost 120 Zetec 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	30/10/2017	Body Style	Hatchback	Last service miles	29,595
Year	2017	Keys	1	MOT Due	23/07/2026
Mileage	82,099 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	3	Doors	5
VIN	WF0AXXWPMMAHC09845	Last service date	26/08/2021		

Last Service - 26.08.2021 at 29595 miles (3 services) Engine rattle when accelerating but runs fine Smoking

### Tyres

NSF	MICHELIN	1.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	Illegal
OSR	MICHELIN	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Dented  
2 Or Less Up To 10mm



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Dented  
With Paint Damage



6: Door nsr  
Chipped  
1 To 5



7: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



8: Bumper Rear Moulding  
Scratched (Painted)  
Over 25mm Thru Paint



9: Tailgate  
Scratched  
Over 25mm Thru Paint



10: Qtr Panel osr  
Chipped  
1 To 5



11: Door osr  
Scratched  
Over 25mm Thru Paint



12: Door osf  
Scratched  
Over 25mm Thru Paint



13: Wing osf  
Chipped  
1 To 5



14: Wheel osf  
Scratched  
Over 50mm

