



VEHICLE INSPECTION REPORT

NA67KUD

Nissan Juke 1.6 DiG-T Nismo RS 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |

nama
GRADE
2

Details

| | | | | | |
|-----------|---------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 26/10/2017 | Body Style | Hatchback | Last service miles | 27,766 |
| Year | 2017 | Keys | 2 | MOT Due | 14/11/2026 |
| Mileage | 59,354 Miles Warranted | Service history | Yes | Gearbox | MANUAL |
| Fuel Type | Petrol | Service documents | Service Book | Gears | 6 |
| Colour | SILVER | Number of stamps | 3 | Doors | 5 |
| VIN | SJNFAAF15U7392290 | Last service date | 20/07/2021 | | |

£90 ADDITIONAL FEE

Last service 20/07/2021 at 27,766 miles- 3 services (1 main dealer)

Tyres

| | | |
|-------|----------|-------|
| NSF | MATADOR | 5.0mm |
| NSR | LANDSAIL | 5.0mm |
| OSF | MATADOR | 4.0mm |
| OSR | KUMHO | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Up To 25mm Thru Paint



2: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



3: Qtr Panel nsr
Chipped
1 To 5



4: Door nsr
Chipped
1 To 5



5: Door nsf
Chipped
1 To 5



6: Wheel nsf
Corroded
Light



7: Bumper Front
Chipped
1 To 5



8: Bonnet
Chipped
1 To 5



9: Bumper Front Moulding
 Scratched (Painted)
 UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
 Average

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |