



VEHICLE INSPECTION REPORT

DE13MVK

Honda Civic 1.8 i-VTEC ES 5dr

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/04/2013	Body Style	Hatchback	Last service miles	59,416
Year	2013	Keys	2	MOT Due	19/05/2027
Mileage	83,405 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	6	Doors	5
VIN	SHHFK2760DU006136	Last service date	11/05/2022		

Last Service - 11.05.2022 at 59416 miles (6 services) Auto stop start not available


Tyres


NSF	MICHELIN	4.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos




1: Seat Back Cover of
Torn
Over 3mm




2: Wheel of
Corroded
Light




3: Wing osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osf
Chipped
1 To 5



6: Door osr
Chipped
Multiple Chips



7: Wheel osr
Corroded
Light



8: Qtr Panel osr
Chipped
1 To 5



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Qtr Panel nsr
Dented
With Paint Damage




12: Wheel nsr
Corroded
Light



13: Door nsr
Chipped
1 To 5



14: Door nsr
Scratched
UpTo 25mm Thru Paint



15: Door nsf
Scratched
Over 25mm Thru Paint



16: Wing nsf
Scratched
UpTo 25mm Thru Paint



17: Wheel nsf
Corroded
Light



18: Bumper Front
Chipped
Multiple Chips




19: Bonnet
Chipped
Multiple Chips



20: A Post os
Chipped
1 To 5



21: Screen Front
Chipped
UpTo 10mm



22: Roof
Chipped
1 To 5



23: A Post ns
Poor Previous Repair
Paint Flake



24: Sill ns
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK