



VEHICLE INSPECTION REPORT

GP19FYU

Volkswagen Golf 1.5 TSI EVO Match 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	28/06/2019	Body Style	Hatchback	Last service miles	12,621
Year	2019	Keys	2	MOT Due	27/06/2026
Mileage	14,351 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	6	Doors	5
VIN	WVVZZZAUZKW184870	Last service date	06/06/2025		

£90 ADDITIONAL FEE

last service 6/6/25 @ 12,621 miles (6 main dealer) Service due message displayed

Tyres

NSF	HANKOOK	1.0mm
NSR	HANKOOK	4.0mm
OSF	HANKOOK	2.0mm
OSR	HANKOOK	4.0mm

Spare

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Chipped
1 To 5



7: Door nsf
Dented
2 Or Less UpTo 10mm



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Tailgate
Scratched
Over 25mm Thru Paint




13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Door osr
Chipped
1 To 5




16: Door osf
Scratched
Over 25mm Thru Paint



17: Wheel osf
Corroded
Light



18: Wing osf
Chipped
1 To 5



19: Roof
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK