

# **VEHICLE INSPECTION REPORT**

DS61SXK

## **BMW 3 Series 318d Exclusive Edition 5dr Step Auto**

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape Caraba
		V5	Present		
Details					
Reg. date	06/01/2012	Keys	2	CAP Clean	£2,550.00
Year	2012	Service history	Yes	CAP Average	£2,100.00
Mileage	116,744 Miles Warranted	Service documents	Service Book	CAP Below	£1,650.00
		Number of stamps	7	Gearbox	AUTOMATIC
Fuel Type	Diesel	Last service date	19/03/2025	Gears	6
Colour	GREY	Last service miles	116.237		
VIN	WBAUT32020F214103	MOT Due	17/04/2026		
Body Style	Estate				

£100 ADDITIONAL FEE Last Service: 19/03/2025 at 116237 miles. (13 services (6 main dealer) ). Book & print.

•	VIES
-	,

NSF	PIRELLI	5.0mm	
NSR	PIRELLI	3.0mm	
OSF	PIRELLI	5.0mm	
OSR	BRIDGESTONE	5.0mm	
Spare			

### **Features**

- Bluetooth connection
- Rear parking sensor
  Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control · Leather seat trim
- Cruise control
- Rear wiper Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation systemRadio/CD
- Climate control
- Rear headrests
- Passenger airbagRemote central locking

#### **Photos**












## **Condition Check**



## **Damage Photos**



1: Wing osf Poor Previous Repair Poor Paint



2: Wheel osf Scratched Over 50mm



3: Door osf Chipped 1 To 5



4: Door osf Chipped Edge Chip



5: Wheel osr Scratched Over 50mm



6: Bumper Rear Poor Previous Repair Paint Flake




7: Qtr Panel nsr Scratched UpTo 25mm Not Thru Paint



8: Wheel nsr Scratched Over 50mm



9: Door nsr Scratched Over 25mm Thru Paint



10: Door nsf Chipped Edge Chip



11: Wheel nsf Scratched Over 50mm



12: Bumper Front Poor Previous Repair Paint Flake



13: Bonnet Chipped 1 To 5



14: Roof Dented Between 10mm + 30mm

### Interior

**Carpet Condition Seat Condition** 

Average Average **Upholstery Condition Odour** 

Average No

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OK		Gearbox 1st and Reverse Test	
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	
Parking Brake	OK	No Excessive Smoking	
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK