



VEHICLE INSPECTION REPORT

CV08AVF

Hyundai Coupe 2.0 SIII 3dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	03/03/2008	Keys	1	CAP Clean	£1,275.00
Year	2008	Service history	Yes	CAP Average	£880.00
Mileage	82,550 Miles Warranted	Service documents	Service Book	CAP Below	£500.00
Fuel Type	Petrol	Number of stamps	14	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	08/02/2023	Gears	4
VIN	KMHHN61DR7U260957	Last service miles	65,707		
Body Style	Coupe	MOT Due	03/03/2026		

£65 ADDITIONAL FEE Last service 08/02/2023 @ 65707 miles (14 SERVICES 1 MAIN DEALER)

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Cruise control
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Isofix child seat anchor points
- Leather seat trim
- PAS
- Electric door mirrors
- Climate control
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Electric sunroof
- Front armrest
- ABS
- Central locking
- Radio/CD
- Opening panoramic glass roof
- Front electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm

No Image


4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Chipped
1 To 5

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Screen Front
Chipped
UpTo 10mm



8: Qtr Panel nsr
Dented
With Paint Damage




9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Boot Lid
Poor Previous Repair
Poor Paint




11: Wheel osr
Scratched
Over 50mm



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door osf
Dented
Over 2 UpTo 10mm



14: Door osf
Scratched
Over 25mm Not Thru Paint

No Image



15: Wing osf
Scratched
Over 25mm Not Thru Paint

16: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		