



VEHICLE INSPECTION REPORT

GU60EEG

Ford Focus 1.8 Zetec 5dr

nama
GRADE 5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	01/09/2010	Body Style	Hatchback	Last service miles	74,653
Year	2010	Keys	2	MOT Due	Expired
Mileage	113,049 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	6	Doors	5
VIN	WF0PXXWDPAS26791	Last service date	22/07/2021		

MOT EXPIRED

Last service 22/07/2021 at 74,653 miles- 6 services (3 main dealer) Book and print Aftermarket radio installed
 Bonnet will not open lock missing
 Exhaust rattling

Tyres

NSF	BUDGET	5.0mm
NSR	APOLLO	5.0mm
OSF	LAUFENN	5.0mm
OSR	APOLLO	5.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Sill ns
Rusted
Over 5mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Cracked
Over 25mm



11: Bumper Reflector osr
Broken
Replace



12: Qtr Panel osr
Dented
With Paint Damage



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
UpTo 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Sill os
Rusted
Over 5mm



17: Wing osf
Rusted
Over 5mm



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK