

VEHICLE INSPECTION REPORT

LD61XAX

Land Rover Range Rover Evoque 2.2 SD4 Dynamic 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details			
Reg. date	13/10/2011	Colour	BLACK
Year	2011	VIN	SALVA2AEXCH612634
Mileage	123,530 Miles Warranted	Body Style	Estate
Fuel Type	Diesel	Keys	2
		Service history	None
		MOT Due	11/03/2027
		Gearbox	AUTOMATIC
		Gears	6

NO SERVICE HISTORY Gearbox fault, judders when selecting gear

Tyres			
NSF	BUDGET		4.0mm
NSR	BUDGET		3.0mm
OSF	BUDGET		2.0mm
OSR	BUDGET		3.0mm
Spare			

Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
Multiple Chips



3: Door osr
Chipped
1 To 5



4: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



5: Wheel osr
Scratched
Up To 50mm



6: Qtr Panel osr
Chipped
1 To 5



7: Bumper Rear
Poor Previous Repair
Paint Flake



8: Qtr Panel nsr
Poor Previous Repair
Poor Paint



9: Wheel nsr
Scratched
Up To 50mm



10: Door nsr
Dented
Over 30mm



11: Door nsf
Chipped
Multiple Chips



12: Other
N/A
N/A



13: Wing nsf
Scratched
Over 25mm Thru Paint



14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
Poor Previous Repair
Poor Paint



16: Bonnet
Poor Previous Repair
Poor Paint



17: Screen Front
Chipped
Up To 10mm



18: Door Moulding of
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		