



VEHICLE INSPECTION REPORT

LC120VS

Ford Focus 1.6 TDCi 115 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	28/06/2012	Body Style	Hatchback	Last service miles	109,255
Year	2012	Keys	2	MOT Due	28/09/2026
Mileage	121,488 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	3	Doors	5
VIN	WF0KXXGCBKCG74484	Last service date	26/06/2024		

£100 ADDITIONAL FEE
LAST SERVICE 26/06/2024 @ 109,225 MILES (3 SERVICES)

Tyres

NSF	MATADOR	5.0mm
NSR	MATADOR	5.0mm
OSF	MATADOR	5.0mm
OSR	MATADOR	Damaged
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Full size spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Tyre osr
Damaged
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: A Post ns
Scratched
UpTo 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Sill Panel Trim ns
Broken
Replace



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Door nsr
Dented
Between 10mm + 30mm



11: Wheel osr
Scratched
Over 50mm



12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: Qtr Panel osr
Dented
Between 10mm + 30mm



14: Wheel osr
Scratched
Over 50mm



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osf
Scratched
UpTo 25mm Thru Paint



18: Wing osf
Scratched
Over 25mm Thru Paint



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK