



VEHICLE INSPECTION REPORT

DV67VNP

Vauxhall Astra 1.4i 16V Design 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	31/12/2017	Body Style	Estate	Last service miles	25,509
Year	2017	Keys	1	MOT Due	30/12/2026
Mileage	71,772 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLACK	Number of stamps	2		
VIN	W0VBD8ED9J8007061	Last service date	01/04/2021		

£100 ADDITIONAL FEE.

Last service 01/04/2021 at 25,509 miles- 2 services Eml light is on
Car been plugged in and detected
Clutch Pedal Position Sensor 'A' Circuit Range/Performance issue
Service due message displayed
Front suspension knocking
Intermittent starter motor fault

Tyres		
NSF	BUDGET	5.0mm
NSR	ROYALBLACK	5.0mm
OSF	BUDGET	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Dented
With Paint Damage



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
With Paint Damage



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
With Paint Damage



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Lamp nsr
Broken
Replace



11: Qtr Panel osr
Dented
With Paint Damage



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Scratched
Over 25mm Thru Paint




14: Door osf
Dented
With Paint Damage



15: Wheel of
Scratched
Over 50mm



16: Wing of
Chipped
1 To 5



17: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK