



VEHICLE INSPECTION REPORT

OU60BZE

Volkswagen Golf 1.6 TDi 105 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/09/2010	Body Style	Hatchback	Last service miles	88,112
Year	2010	Keys	2	MOT Due	21/01/2027
Mileage	158,888 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	5
Colour	SILVER	Number of stamps	9	Doors	5
VIN	WVVZZZ1KZAW413829	Last service date	23/05/2019		

£90 ADDITIONAL FEE

LAST SERVICE 23/05/19 @ 88,112 MILES (9 MAIN DEALER SERVICES) Driver door getting stuck

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Cruise control
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- Curtain airbags
- Rear airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Dented
Over 30mm



3: Door osf
Scratched
Over 25mm Not Thru Paint



4: Door osf
Dented
2 Or Less Up To 10mm



5: Door osf
Chipped
Edge Chip



6: Door osr
Chipped
1 To 5



7: Wheel osr
Corroded
Light



8: Bumper Rear
Poor Previous Repair
Paint Flake



9: Tailgate
Chipped
1 To 5



10: Qtr Panel nsr
Dented
Over 30mm



11: Wheel nsr
Corroded
Light



12: Door nsr
Scratched
Over 25mm Not Thru Paint



13: Sill ns
Dented
Over 30% Of Panel



14: Door nsf
Scratched
Over 25mm Not Thru Paint



15: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



16: Wing nsf
Dented
Between 10mm + 30mm



17: Wheel nsf
Corroded
Light



18: Bumper Front
Scratched
Over 100mm Thru Paint



19: Bonnet
Chipped
Multiple Chips



20: A Post os
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK