



VEHICLE INSPECTION REPORT

CF17ODK

Kia Soul 1.6 GDi 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	18/08/2017	Body Style	Hatchback	Last service miles	56,675
Year	2017	Keys	2	MOT Due	17/08/2026
Mileage	63,115 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	8	Doors	5
VIN	KNAJP812LJ7525659	Last service date	11/08/2025		

Last Service - 11.08.2025 at 56675 miles (8 services 6 main dealer) Reverse camera image blurry
 INTERMITTENT OIL LIGHT ON

Tyres


NSF	BUDGET	2.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	SUNNY	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Trip computer
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Alarm
- Cruise control
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Climate control
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Tailgate
Scratched
UpTo 25mm Thru Paint



9: Qtr Panel Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



10: Door osr
Dented
Between 10mm + 30mm




11: Door osr
Scratched
Over 25mm Thru Paint



12: Door osf
Dented
Between 10mm + 30mm



13: Wheel osf
Scratched
Over 50mm



14: Screen Front
Chipped
UpTo 10mm



15: Qtr Panel nsr
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK