



# VEHICLE INSPECTION REPORT

**LG17YYC**

## Kia Ceed 1.6 CRDi ISG 2 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	26/06/2017	Body Style	Hatchback	Last service miles	47,993
Year	2017	Keys	2	MOT Due	05/08/2026
Mileage	104,779 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Electronic / Online	Gears	7
Colour	WHITE	Number of stamps	4	Doors	5
VIN	U5YHN516VHL292720	Last service date	16/06/2022		

### £100 ADDITIONAL FEE

last service 16/6/22 @ 47,993 miles (4 main dealer) confirmed by West Sussex Motors Kia, Washington Engine rattling at idle

### Tyres


NSF	LAUFENN	5.0mm
NSR	LAUFENN	5.0mm
OSF	LAUFENN	5.0mm
OSR	LAUFENN	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsf  
Dented  
Over 30mm



5: Sill ns  
Dented  
Over 30mm



6: Door nsr  
Dented  
Between 10mm + 30mm



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



10: Bumper Rear  
Cracked  
Over 25mm



11: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



12: Wheel osr  
Scratched  
Over 50mm



13: Door osr  
Chipped  
Edge Chip




14: Door osf  
Chipped  
Edge Chip



15: Wheel osf  
Scratched  
Over 50mm



16: Wing osf  
Scratched  
Over 25mm Thru Paint



17: Roof  
Chipped  
Edge Chip

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK