



# VEHICLE INSPECTION REPORT

**ND18DPF**

## Nissan Qashqai 1.6 dCi N-Connecta 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	11/06/2018	Body Style	Hatchback	MOT Due	10/03/2027
Year	2018	Keys	2	Gearbox	CVT
Mileage	61,254 Miles Warranted	Service history	Yes	Gears	1
Fuel Type	Diesel	Service documents	Service Book	Doors	5
Colour	SILVER	Number of stamps	2		
VIN	SJNFDAJ11U2342808	Last service miles	17,043		

Last Service - 02.09.2020 at 17043 miles (2 main dealer services)

### Tyres




NSF	RIKEN	3.0mm
NSR	WESTLAKE	5.0mm
OSF	RIKEN	3.0mm
OSR	CONTINENTAL	6.0mm
Spare		

### Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Over 30mm




2: Bumper Front  
Scratched  
25 to 100mm Thru Paint




3: Wing nsf  
Dented  
With Paint Damage



4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Chipped  
Multiple Chips



6: Door nsf  
Dented  
Between 10mm + 30mm



7: Door nsr  
Scratched  
Up To 25mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



11: Qtr Panel osr  
Dented  
Between 10mm + 30mm



12: Qtr Panel osr  
Chipped  
1 To 5



13: Wheel osr  
Corroded  
Light



14: Door osr  
Dented  
Over 30mm



15: Door osf  
Chipped  
Multiple Chips



16: Wing osf  
Chipped  
1 To 5



17: Wheel osf  
Scratched  
Over 50mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK