



VEHICLE INSPECTION REPORT

MK13BMY

Kia Venga 1.4 EcoDynamics 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE 5

Details

Reg. date	05/03/2013	Body Style	Hatchback	Last service miles	19,924
Year	2013	Keys	2	MOT Due	17/12/2026
Mileage	93,590 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	4	Doors	5
VIN	U5YEH811LDL048803	Last service date	10/02/2017		

£100 ADDITIONAL FEE

Last service 10/02/2017 at 19,924 miles- 4 services (2 main dealer)

Tyres

NSF	BUDGET	4.0mm
NSR	INVOVIC	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear armrest
- Metallic Paint
- Isofix child seat anchor points
- Alarm
- PAS
- Trip computer
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Radio/CD
- Climate control
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Bumper Front Grill
Broken
Replace



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Door nsr
Dented
Between 10mm + 30mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint




12: Tailgate
Scratched
UpTo 25mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osr
Dented
Between 10mm + 30mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Scratched
Over 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
Over 25mm Thru Paint



19: Screen Front
Chipped
UpTo 10mm



20: Seat Base Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK