



VEHICLE INSPECTION REPORT

BJ63TWZ

Ford Focus 1.6 TDCi 115 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	01/11/2013	Body Style	Hatchback	Last service miles	101,321
Year	2013	Keys	2	MOT Due	03/12/2026
Mileage	126,512 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	7	Doors	5
VIN	WF0KXXGCBKDC56449	Last service date	11/05/2023		

£100 ADDITIONAL FEE

Last service 11/05/2023 at 101,321 miles- 7 services (6 main dealer) Book and print

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Space saver spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Service indicator
- Electric door mirrors
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Wing nsf
Chipped
1 To 5



6: A Post ns
Dented
2 Or Less UpTo 10mm



7: A Post ns
Chipped
1 To 5



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Rusted



10: Door nsr
Dented
Over 30mm



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Tailgate
Rusted
Over 5mm



14: Rear TowEye Cvr
Missing
Replace



15: Qtr Panel osr
Scratched
Rusted



16: Door osr
Dented
Between 10mm + 30mm



17: Door osf
Dented
Between 10mm + 30mm



18: Wheel osf
Scratched
Over 50mm



19: Roof
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK