



# VEHICLE INSPECTION REPORT

**HN67EUV**

## Peugeot 2008 1.2 PureTech Allure 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	24/01/2018	Body Style	Hatchback	Last service miles	105,503
Year	2018	Keys	2	MOT Due	16/02/2027
Mileage	106,353 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	RED	Number of stamps	4	Doors	5
VIN	VF3CUHMZ6HY183793	Last service date	06/05/2026		

### £100 ADDITIONAL FEE

Last service 06/05/2026 at 105,503 miles- 4 services

Cambelt replaced 24/07/2025 at 90,026 miles EML light is on car has been plugged in and detects catalyst system efficiency below threshold bank 1

### Tyres




NSF	BRIDGESTONE	3.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Corroded  
Light



2: Door osf  
Scratched  
Over 25mm Thru Paint



3: Door osr  
Chipped  
1 To 5



4: Door osr  
Scratched  
Up To 25mm Thru Paint



5: Qtr Panel osr  
Dented  
With Paint Damage



6: Wheel osr  
Corroded  
Light



7: Tailgate  
Dented  
Over 30mm



8: Wheel nsr  
Corroded  
Light



9: Door nsr  
Scratched  
UpTo 25mm Thru Paint



10: Door nsr  
Chipped  
1 To 5



11: Door nsr  
Dented  
2 Or Less UpTo 10mm



12: Door nsf  
Chipped  
1 To 5



13: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



14: Wing nsf  
Dented  
With Paint Damage



15: Wheel nsf  
Corroded  
Light



16: Bumper Front  
Scratched  
25 to 100mm Thru Paint



17: Bonnet  
Poor Previous Repair  
Poor Colour



18: A Post os  
Chipped  
1 To 5

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK