



VEHICLE INSPECTION REPORT

WK65VFB

Vauxhall Zafira 1.4T SRi 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	06/11/2015	Body Style	MPV	Last service miles	76,657
Year	2015	Keys	2	MOT Due	17/12/2026
Mileage	80,807 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	9		
VIN	W0LPD9EC8G1001975	Last service date	04/12/2025		

Last Service -04.12.2025 at 76657 miles (9 services) Pulley noise
 Exhaust blowing
 Misfires

Tyres


NSF	BUDGET	5.0mm
NSR	RAPID	5.0mm
OSF	BUDGET	5.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check




Damage Photos



1: Fascia Trim
Damaged
Replace



2: Bonnet
Dented
Over 30mm



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Dented
With Paint Damage



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Tailgate
Scratched
UpTo 25mm Thru Paint



13: Qtr Panel osr
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm



15: Door osr
 Scratched
 Over 25mm Thru Paint



16: Door osf
 Scratched
 Over 25mm Thru Paint



17: Wing osf
 Dented
 Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK