



VEHICLE INSPECTION REPORT

YC14XFL

Volvo V60 D6 AWD Plug-in Hybrid Pure Limited 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/06/2014	Body Style	Estate	Last service miles	129,277
Year	2014	Keys	1	MOT Due	21/02/2027
Mileage	161,777 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	7		
VIN	YV1GWAA50E1195372	Last service date	04/01/2023		

£100 ADDITIONAL FEE

LAST SERVICE 04/01/2023 @ 129,277 MILES (7 SERVICES, 6 MAIN DEALER) Service overdue message displayed

DSTC service required

City safety service required

Headlamp system malfunction service required

Alarm system malfunction

Abs light is on

Tyres

NSF	POWERTRAC	5.0mm
NSR	GOODRIDE	5.0mm
OSF	POWERTRAC	5.0mm
OSR	GOODRIDE	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Electric sunroof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Chipped
1 To 5



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel osr
Chipped
1 To 5



11: Wheel osr
Scratched
Over 50mm



12: Wheel nsr
Scratched
Over 50mm



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Chipped
Edge Chip



15: Wing of
Chipped
1 To 5



16: Wheel of
Scratched
Over 50mm



17: Switches And Controls
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		