



VEHICLE INSPECTION REPORT

DN19EYF

Vauxhall Mokka X 1.4T ecoTEC Active 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	31/03/2019	Body Style	Hatchback	Last service miles	5,090
Year	2019	Keys	2	MOT Due	23/01/2027
Mileage	74,558 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	1	Doors	5
VIN	W0VJC7E83KB843691	Last service date	26/01/2023		

£90 ADDITIONAL FEE

Last service 26/01/2023 at 5090 miles- 1 service Eml light is on

Car been plugged in and detected

Catalyst System Efficiency Below Threshold (Bank 1)

Possible central locking fault

Tyres

NSF	SUNNY	6.0mm
NSR	AVON	4.0mm
OSF	SUNNY	6.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Cloth seat trim
- PAS
- Digital radio
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Up To 50mm



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Chipped
1 To 5



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel osr
Dented
With Paint Damage



11: Door osr
Dented
With Paint Damage



12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Wing osf
Poor Previous Repair
Rippled UpTo 30%



14: Tailgate
Poor Previous Repair
Poor Paint



15: Bumper Front Moulding
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK