



VEHICLE INSPECTION REPORT

HN67KKZ

Kia Stinger GT S

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	14/11/2017	Body Style	Hatchback	Last service miles	92,862
Year	2017	Keys	2	MOT Due	29/06/2026
Mileage	118,790 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	8
Colour	RED	Number of stamps	4	Doors	5
VIN	KNAE551CMJ6006313	Last service date	10/07/2024		

£100 ADDITIONAL FEE
 LAST SERVICE 10/07/2024 @ 92,862 MILES (4 SERVICES, ALL MAIN DEALER)

Tyres


NSF	MICHELIN	4.0mm
NSR	GOODYEAR	4.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	Illegal
Spare		

Features


- Bluetooth connection
- Park assist camera
- Body coloured bumpers
- Climate control
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable drivers seat
- Heated front seat
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Navigation system
- Radio/CD
- Air conditioning
- Front armrest
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear electric windows
- Drivers airbag
- Central locking
- Rear headrests
- Passenger airbag
- Remote central locking
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Wing of
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Dented
With Paint Damage



6: Wheel osr
Scratched
Over 50mm



7: Qtr Panel osr
Dented
Over 30mm



8: Bumper Rear
Dented
With Paint Damage



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint




10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Scratched
UpTo 25mm Thru Paint



12: Other
N/A
N/A




13: Door nsf
Dented
Between 10mm + 30mm




14: Door nsf
Chipped
Edge Chip



15: Wheel nsf
Scratched
Up To 50mm




16: Bumper Front
Scratched
25 to 100mm Thru Paint



17: Bumper Front
Chipped
Multiple Chips



18: Bonnet
Chipped
1 To 5



19: Other
N/A
N/A



20: Other
N/A
N/A



21: Roof
 Dented
 2 Or Less UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		