



VEHICLE INSPECTION REPORT

NL60MFE

Honda CR-V 2.2 i-DTEC EX 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	29/09/2010	VIN	SHSRE6770AU016997	Number of stamps	8
Year	2010	Body Style	Estate	Last service date	31/08/2023
Mileage	138,329 Miles Warranted	Keys	2	MOT Due	29/09/2026
Fuel Type	Diesel	Service history	Yes	Gearbox	MANUAL
Colour	SILVER	Service documents	Service Book	Gears	6

LAST SERVICE 31/08/2023 @ UNKNOWN MILEAGE (8 SERVICES, 5 MAIN DEALER - BOOK & PRINT)

Tyres


NSF	NEXEN	3.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	3.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Bonnet
Dented
Between 10mm + 30mm



3: Bonnet
Chipped
1 To 5



4: Bumper Front
Dented
With Paint Damage



5: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsr
Chipped
1 To 5



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Door osr
Scratched
UpTo 25mm Thru Paint



16: Door osf
Chipped
1 To 5



17: Wing osf
Scratched
UpTo 25mm Thru Paint



18: Screen Front
Chipped
UpTo 10mm



19: Glass Roof
Cracked
Replace



20: B Post os
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK