



# VEHICLE INSPECTION REPORT

**LV62XPU**

## Mercedes-Benz C Class C180 BlueEFFICIENCY Executive SE 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	28/01/2013	Body Style	Saloon	Last service miles	65,532
Year	2013	Keys	2	MOT Due	16/03/2027
Mileage	117,034 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	SILVER	Number of stamps	5	Doors	4
VIN	WDD2040312A816565	Last service date	21/08/2020		

LAST SERVICE 21/08/2020 @ 65,532 MILES (5 SERVICES, ALL MAIN DEALER)

### Tyres

NSF	AVON	5.0mm
NSR	AVON	5.0mm
OSF	AVON	5.0mm
OSR	AVON	5.0mm

Spare

## Features


- Bluetooth connection
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Leather seat trim
- Navigation system
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5




2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
Multiple Chips



5: Screen Front  
Chipped  
UpTo 10mm



6: Door nsf  
Dented  
Over 30mm



7: Door nsf  
Chipped  
Edge Chip



8: Door nsr  
Dented  
Between 10mm + 30mm



9: Wheel nsr  
Scratched  
Over 50mm



10: Bumper Rear  
Dented  
With Paint Damage



11: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



12: Wheel osr  
Scratched  
Up To 50mm



13: Door osr  
Scratched  
UpTo 25mm Thru Paint



14: Door osf  
Scratched  
UpTo 25mm Thru Paint



15: Wheel osf  
 Scratched  
 Over 50mm



16: Seat Base Cover nsf  
 Torn  
 Over 3mm



17: Seat Base Cover osf  
 Torn  
 Over 3mm

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
 Poor

**Upholstery Condition**  
**Odour**

Average  
 No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK