



VEHICLE INSPECTION REPORT

GK66SVY

MG Mg 3 3 STYLE LUX VTI-TECH

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	22/09/2016	Body Style	Hatchback	Last service miles	47,133
Year	2016	Keys	2	MOT Due	20/11/2026
Mileage	72,187 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	4	Doors	5
VIN	SDPZ1CBDAGS037808	Last service date	03/09/2019		

Last Service - 03.09.2019 at 47133 miles (4 services)

Tyres

NSF	BUDGET	4.0mm
NSR	RIKEN	5.0mm
OSF	BUDGET	4.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Traction control
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Seat Back Cover osf
Scuffed
Over 25mm



3: Bonnet
Chipped
1 To 5



4: Bumper Front
Poor Previous Repair
Paint Flake



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Dented
With Paint Damage



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
2 Or Less UpTo 10mm



17: Door osr
Chipped
1 To 5



18: Door osf
Scratched
Over 25mm Thru Paint



19: Door osf
Dented
2 Or Less UpTo 10mm



20: Wing osf
Scratched
Over 25mm Thru Paint



21: Wheel of
Scratched
Over 50mm



22: Switches And Controls
Broken
Replace



23: Door Pad of
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK