



VEHICLE INSPECTION REPORT

LP15LWC

Jaguar XE 2.0d SE 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	29/06/2015	Body Style	Saloon	Last service miles	26,031
Year	2015	Keys	2	MOT Due	05/01/2027
Mileage	55,901 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	RED	Number of stamps	2	Doors	4
VIN	SAJAB4AN7GA908967	Last service date	19/07/2018		

£90 ADDITIONAL FEE

LAST SERVICE 19/07/2018 @ 26,031 MILES (2 SERVICES, BOTH MAIN DEALER)

Tyres

NSF	UNIROYAL	5.0mm
NSR	UNIROYAL	5.0mm
OSF	UNIROYAL	5.0mm
OSR	UNIROYAL	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Cloth seat trim
- Front parking sensor
- Steering wheel mounted controls
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Digital radio
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wing nsf
Chipped
1 To 5



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Chipped
1 To 5



8: Bumper Rear
Chipped
1 To 5



9: Qtr Panel osr
Chipped
1 To 5



10: Door osr
Dented
Between 10mm + 30mm



11: Door osr
Chipped
1 To 5



12: Door osf
Dented
With Paint Damage



13: Wing osf
Scratched
Up To 25mm Thru Paint



14: Roof
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK