

### VEHICLE INSPECTION REPORT

LN170WR

## Lexus RX 450h 3.5 Premier 5dr CVT [Sunroof]

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape.
		V5	Present		
Details					
Reg. date	01/03/2017	Keys	2	CAP Clean	£17,800.00
Year	2017	Service history	Yes	CAP Average	£16,450.00
Mileage	64,860 Miles Warranted	Service documents	Service Book	CAP Below	£15,100.00
		Number of stamps	9	Gearbox	CVT
Fuel Type	Hybrid Electric	Last service date	17/03/2025	Gears	1
Colour	BLACK	Last service miles	62,960		
VIN	JTJBGMCA502020066	MOT Due	05/04/2026	<del></del>	
Body Style	Estate				

Last Service - 17.03.2025 at 62960 miles (9 main dealer services)

т	٠.,	
	уı	62

NSF	YOKOHAMA	3.0mm	
NSR	BUDGET	4.0mm	
OSF	YOKOHAMA	4.0mm	
OSR	YOKOHAMA	4.0mm	
Spare			

#### **Features**

- Bluetooth connection
- Navigation system
- · Rear wiper
- Audio remote control
- · Electric door mirrors
- Climate control
- · Front electric windows
- · Rear headrests
- Drivers airbag Traction control
- · Alloy wheels

- Cruise control
- Park assist camera
- Steering wheel mounted controls

  Auxiliary input socket

  Electric sunroof

  •

- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- · Central locking

- · Front parking sensor
- PAS
- Telephone

- Auxiliary input socket
   Electric sunroof
   Electrically adjustable drivers seat
   Digital radio
   Opening panoramic glass roof
   Electrically adjustable passenger seat
  - Height adjustable drivers seat
  - 3x3 point rear seat belts
  - Passenger airbag
  - Remote central locking
- · Heated front seat
- · Rear parking sensor
- Trip computer
  Body coloured bumpers
  Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim

#### **Photos**










### **Condition Check**



### **Damage Photos**



1: Bumper Rear Scratched 25 to 100mm Thru Paint No Image

2: Bumper Rear Scratched Over 25mm Not Thru Paint


## No Image

3: Boot Lid Scratched Over 25mm Not Thru Paint



4: Wheel osr Scratched Up To 50mm

# No Image





6: Door osr Chipped Multiple Chips



7: Door osf Chipped Multiple Chips



8: Wheel osf Scratched Up To 50mm

# No Image

9: Wing osf Scratched



11: Bonnet Chipped 1 To 5



Chipped Multiple Chips



12: Wheel nsf Scratched Up To 50mm



13: Door nsf Chipped 1 To 5



14: Door nsr Chipped 1 To 5

### Interior

Carpet Condition - Upholstery Condition - Odour -

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs		Gearbox 1st and Reverse Test	
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		