

VEHICLE INSPECTION REPORT

NJ68FUB

BMW X2 sDrive 20i Sport 5dr Step Auto

Inspection		Vehicle	Margin		nama
Serious Damage?	No	VAT			2 Grape
		V5	Present		
Details					
Reg. date	27/09/2018	Keys	2	CAP Clean	£10,850.00
Year	2018	Service history	Yes	CAP Average	£9,650.00
Mileage	86,360 Miles Warranted	Service documents	Printout	CAP Below	£8,525.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	AUTOMATIC
Colour	WHITE	Last service date	25/06/2024	Gears	7
VIN	WBAYH32030EH09423	Last service miles	69,264	Doors	5
Body Style	Hatchback	MOT Due	26/09/2025		

Last service 25/06/2024 @ 69264 miles (1 SERVICE) Eml on

NSF	BUDGET	2.0mm	
NSR	BUDGET	3.0mm	
OSF	BUDGET	3.0mm	
OSR	BUDGET	3.0mm	
Spare			

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls Trip computer
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- · Central locking

- Cruise control
- PAS
- Electric door mirrors
- Climate control
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Audio remote control
- Electric sunroof
- · Front head restraints
- Solid Paint
- Passenger airbag
- Leather seat trim

- Navigation system
- Rear wiper
- Digital radio
- Opening panoramic glass roof Electrically adjustable drivers seat • Electrically adjustable passenger
 - seat • Height adjustable drivers seat
 - 3x3 point rear seat belts
 - Traction control
 - Alloy wheels

Photos













Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Chipped Multiple Chips



3: Wheel nsf Scratched Over 50mm



4: Door nsf Chipped 1 To 5



5: Door nsr Dented 2 Or Less UpTo 10mm



6: Wheel nsr Scratched Over 50mm



7: Bumper Rear Scratched 25 to 100mm Thru Paint



8: Wheel osr Scratched Over 50mm

No Image

9: Qtr Panel osr Scratched Over 25mm Not Thru Paint



10: Door osr Chipped 1 To 5

No Image

11: Door osfScratchedOver 25mm Not Thru Paint



12: Wheel osf Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OK	Gearbox 1st and Reverse Test OK
Brakes OK	Clutch Slip Test from Static OK
Turbo Boosting OK	Gearbox Static Gear Selection (engine running) OK
Parking Brake OK	No Excessive Smoking OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		