



VEHICLE INSPECTION REPORT

WU63YPV

Ford Focus 1.0 125 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/09/2013	Body Style	Hatchback	Last service miles	30,110
Year	2013	Keys	2	MOT Due	14/04/2027
Mileage	80,985 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Electronic / Online	Gears	6
Colour	RED	Number of stamps	2	Doors	5
VIN	WF0KXXGCBKCT37507	Last service date	27/05/2021		

LAST SERVICE 27/05/2021 @ 30,110 MILES (2 SERVICES, BOTH MAIN DEALER - CONFIRMED BY ALLEN FORD SWINDON)

Tyres

NSF	BUDGET	5.0mm
NSR	GOODRIDE	6.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm

Spare

Features


- Bluetooth connection
- Radio/CD
- Space saver spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint




3: Other
N/A
N/A



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Chipped
1 To 5



7: Handle Outer nsf
Scratched (Painted)
Up To 25mm Thru Paint



8: Door nsr
Chipped
1 To 5



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Tailgate Trim Panel
Scratched (Painted)
Over 25mm Thru Paint



11: Wheel osf
Scratched
Over 50mm



12: Door osf
Chipped
Edge Chip



13: Door osf
Dented
With Paint Damage



14: Wing osf
Poor Previous Repair
Poor Paint



15: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint




16: Wheel osf
Scratched
Over 50mm



17: Screen Front
Chipped
Over 10mm



18: Roof
Scratched
Over 25mm Thru Paint



19: Fogdriving Lamp osf
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK