

# VEHICLE INSPECTION REPORT

**GU64UMF**

## Volkswagen UP 1.0 Move Up 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	04/10/2014	Body Style	Hatchback	Last service miles	44,520
Year	2014	Keys	2	MOT Due	03/10/2026
Mileage	47,070 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	7	Doors	5
VIN	VWVZZZAAZFD013550	Last service date	30/09/2025		

£90 ADDITIONAL FEE

Last service 30/09/2025 at 44,520 miles- 7 services (3 main dealer)

### Tyres


NSF	BUDGET	4.0mm
NSR	LAUFENN	6.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	8.0mm
Spare		

## Features


- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- Drivers airbag
- Cloth seat trim
- Rear wiper
- Air conditioning
- Front head restraints
- Metallic Paint
- Passenger airbag
- Steel wheels
- Trip computer
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Alarm
- Radio/CD
- Folding rear seats
- Rear headrests
- ABS
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Poor Previous Repair  
Poor Paint



3: Wing nsf  
Dented  
Between 10mm + 30mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint




5: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



6: Door nsf  
Dented  
Between 10mm + 30mm



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



9: Bumper Rear  
Dented  
With Paint Damage



10: Qtr Panel osr  
Poor Previous Repair  
Poor Paint



11: B Post os  
Scratched  
Over 25mm Thru Paint



12: Handle Outer osr  
Scratched (Painted)  
UpTo 25mm Thru Paint



13: Door osf  
Dented  
With Paint Damage



14: Roof  
Chipped  
1 To 5



15: B Post os  
Dented  
Between 10mm + 30mm



16: Wing osf  
Scratched  
Over 25mm Thru Paint

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK