



VEHICLE INSPECTION REPORT

HY69RUH

Volkswagen Golf 1.5 TSI EVO 150 R-Line 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	19/09/2019	Body Style	Hatchback	Last service miles	107,456
Year	2019	Keys	2	MOT Due	18/09/2026
Mileage	111,297 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	7	Doors	5
VIN	WVVZZZAUZKW164909	Last service date	31/03/2026		

£90 ADDITIONAL FEE

Last service 31/03/2026 at 107,456 miles- 7 services Engine runs fine, but tapping noise from engine.

Tyres


NSF	BRIDGESTONE	4.0mm
NSR	DUNLOP	4.0mm
OSF	BRIDGESTONE	3.0mm
OSR	DUNLOP	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Lumbar support
- Steering wheel rake adjustment
- ABS
- Alarm
- Cruise control
- PAS
- Trip computer
- Air conditioning
- Front electric windows
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Climate control
- Front head restraints
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Poor Previous Repair
Poor Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsf
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Chipped
1 To 5



11: Tailgate
Dented
Between 10mm + 30mm



12: Wheel osr
Scratched
Up To 50mm



13: Door osf
Chipped
Edge Chip



14: Door osf
Scratched
Up To 25mm Thru Paint



15: Wheel osf
Scratched
Over 50mm



16: Screen Front
Chipped
UpTo 10mm



17: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK