



VEHICLE INSPECTION REPORT

LL18HSD

Audi A5 2.0 TFSI S Line 2dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	25/05/2018	Body Style	Convertible	Last service miles	65,606
Year	2018	Keys	1	MOT Due	07/04/2027
Mileage	75,595 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	7		
VIN	WAUZZZF59JN017062	Last service date	04/12/2025		

£90 ADDITIONAL FEE

Last service 04/12/2025 at 65,606 miles- 7 main dealer services

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	3.0mm
OSF	PIRELLI	3.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Trip computer
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Alarm
- Cruise control
- PAS
- Radio/CD
- Heated door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Lumbar support
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Partial leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front electric windows
- Rear electric windows
- Metallic Paint
- Insurance telematics
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Wing nsf
Scratched
Up To 25mm Thru Paint



4: Wheel nsf
Scratched
Up To 50mm



5: Door nsf
Dented
Over 30mm



6: Qtr Panel nsr
Dented
Over 30mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



9: Bumper Rear
Dented
Between 10mm + 30mm



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint



12: Door osf
Dented
Over 30mm



13: Wing osf
Chipped
1 To 5



14: Sunvisor ns
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		