



VEHICLE INSPECTION REPORT

VK61NLU

Nissan Micra 1.2 DiG-S Acenta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	19/09/2011	Body Style	Hatchback	Last service miles	77,130
Year	2011	Keys	2	MOT Due	19/09/2026
Mileage	82,331 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	WHITE	Number of stamps	6	Doors	5
VIN	MDHFEUK13U0002086	Last service date	18/09/2025		

£100 ADDITIONAL FEE
 LAST SERVICE 18/09/2025 @ 77,130 MILES (6 SERVICES, 4 MAIN DEALER)

Tyres

NSF	HANKOOK	5.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Digital radio
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Space saver spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Roof
Poor Previous Repair
Paint Flake



5: Wing nsf
Dented
Between 10mm + 30mm



6: Door Moulding nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Chipped
1 To 5



8: Handle Outer nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Door Moulding nsr
Scratched (Painted)
Over 25mm Thru Paint



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
With Paint Damage



12: Bumper Rear
Dented
With Paint Damage



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Dented
Over 30mm



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
Over 30mm



17: Door osr
Scratched
Over 25mm Thru Paint



18: Door osf
Dented
Over 30mm



19: Wheel osf
Scratched
Over 50mm



20: Door Mirror Assy osf
Broken
Replace



21: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK