



VEHICLE INSPECTION REPORT

VO20SYJ

Vauxhall Grandland X 1.6 Hybrid4 300 Ultimate Nav 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/03/2020	Body Style	Hatchback	Last service miles	56,377
Year	2020	Keys	2	MOT Due	19/04/2027
Mileage	78,441 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	8
Colour	BLUE	Number of stamps	4	Doors	5
VIN	W0VZ45GB4LS015129	Last service date	09/01/2025		

Last service 09/01/2025 at 56,377 miles- 4 main dealer services Type 2 charging cable

Tyres

NSF	TRIANGLE	7.0mm
NSR	TRIANGLE	5.0mm
OSF	TRIANGLE	6.0mm
OSR	TRIANGLE	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Folding rear seats
- Height adjustable drivers seat
- Rear headrests
- 3x3 point rear seat belts
- Lane departure warning
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front armrest
- Lumbar support
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Trip computer
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Radio/CD
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Alarm

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wheel nsf
Scrapped
Over 50mm




4: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Scrapped
Over 25mm Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Scrapped
Up To 25mm Thru Paint



8: B Post ns
Dented
Between 10mm + 30mm



9: Tailgate
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
25 to 100mm Thru Paint




11: Qtr Panel osr
Dented
Between 10mm + 30mm



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Chipped
1 To 5



15: Door osf
Scratched
UpTo 25mm Thru Paint



16: Door osf
Chipped
Edge Chip



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Up To 50mm



19: B Post os
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK