



VEHICLE INSPECTION REPORT

DX16ZRG

Vauxhall Insignia 2.0 CDTi [170] ecoFLEX SRi Nav 5dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/04/2016	Body Style	Hatchback	Last service miles	99,631
Year	2016	Keys	2	MOT Due	30/08/2026
Mileage	107,730 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	7	Doors	5
VIN	W0LGS6E13G1088249	Last service date	15/05/2025		

£90 ADDITIONAL FEE

LAST SERVICE 15/05/2025 @ 99,631 MILES (7 SERVICES, 2 MAIN DEALER) Service due and oil change due message displayed

Tyres


NSF	AUTOGREEN	5.0mm
NSR	AUTOGREEN	6.0mm
OSF	AUTOGREEN	5.0mm
OSR	AUTOGREEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Bumper Front Grill
Broken
Replace



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: A Post ns
Scratched
Over 25mm Thru Paint



8: Door nsf
Poor Previous Repair
Rippled Up To 30%



9: Door nsr
Dented
With Paint Damage



10: Qtr Panel nsr
Poor Previous Repair
Poor Paint



11: Wheel nsr
Scratched
Up To 50mm



12: Bumper Rear
Poor Previous Repair
Poor Paint



13: Tailgate
Scratched
Up To 25mm Thru Paint



14: Qtr Panel osr
Poor Previous Repair
Poor Paint



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Dented
With Paint Damage



17: Wing osf
Dented
With Paint Damage



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Scratched
Rusted

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK