



VEHICLE INSPECTION REPORT

LG12WLB

Hyundai Santa Fe 2.2 CRDi Premium 5dr [7 Seats]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	03/03/2012	Keys	2	CAP Clean	£2,275.00
Year	2012	Service history	Yes	CAP Average	£1,850.00
Mileage	96,081 Miles Warranted	Service documents	Printout	CAP Below	£1,425.00
Fuel Type	Diesel	Number of stamps	2	Gearbox	MANUAL
Colour	GREY	Last service date	07/11/2022	Gears	6
VIN	KMHS81XNCU864205	Last service miles	75,190		
Body Style	Estate	MOT Due	30/01/2026		

£100 ADDITIONAL FEE. Last Service: 07/11/2022 at 75190 miles. (2 services) Radio display broken
Eml light on
Front bumper out of line
Front end knocking when driving

Tyres


NSF	GT RADIAL	5.0mm
NSR	TIGAR	5.0mm
OSF	GT RADIAL	5.0mm
OSR	TIGAR	5.0mm
Spare		

Features


- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Navigation system
- Telephone
- Towbar
- Front electric windows
- ABS
- Central locking
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos




1: Wheel osf
Corroded
Light



2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Wing osf
Chipped
1 To 5



4: Door osf
Scratched
Over 25mm Not Thru Paint



5: Door osr
Chipped
Multiple Chips



6: Wheel osr
Corroded
Light



7: Qtr Panel osr
Chipped
1 To 5



8: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint




10: Tailgate
Dented
With Paint Damage



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Wheel nsr
Corroded
Light



13: Door nsr
Scratched
Over 25mm Not Thru Paint



14: Door nsf
Scratched
Over 25mm Not Thru Paint



15: Wing nsf
Scratched
Over 25mm Not Thru Paint



16: Wheel nsf
Corroded
Light



17: Bumper Front
Scratched
25 to 100mm Thru Paint



18: Bumper Front
Scratched
Over 25mm Not Thru Paint



19: Bonnet
Chipped
1 To 5



20: Seat Base Cover osf
Torn
Over 3mm



21: Seat Back Cover nsr
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK