

# VEHICLE INSPECTION REPORT

**SC64UYG**

## Dacia Duster 1.6 Access 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	23/12/2014	Body Style	Hatchback	MOT Due	21/09/2026
Year	2014	Service history	Yes	Gearbox	MANUAL
Mileage	133,367 Miles Warranted	Service documents	Service Book	Gears	5
Fuel Type	Petrol	Number of stamps	1	Doors	5
Colour	BLUE	Last service date	02/11/2017		
VIN	UV1HSDC5500000005	Last service miles	19,430		

Last service 02/11/2017 at 19,430 miles- 1 service


### Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- PAS
- Roof rails
- Front electric windows
- 3x3 point rear seat belts
- Side airbags
- Steel wheels
- Rear wiper
- Air conditioning
- Front head restraints
- ABS
- Alarm
- Radio/CD
- Climate control
- Steering wheel rake adjustment
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Folding rear seats
- Metallic Paint
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Scuffed  
Over 25mm



2: Seat Back Cover osf  
Scuffed  
UpTo 25mm



3: Seat Back Cover nsf  
Torn  
Over 3mm



4: A Post os  
Chipped  
1 To 5




5: Wing osf  
Scratched  
Over 25mm Thru Paint




6: Bonnet  
Scratched  
Over 25mm Thru Paint



7: Bumper Front  
Scratched  
Over 100mm Thru Paint



8: Wing nsf  
Scratched  
Over 25mm Thru Paint



9: Screen Front  
Chipped  
Over 10mm



10: Door nsf  
Scratched  
Over 25mm Thru Paint



11: Sill ns  
Rusted  
Over 5mm



12: Door nsr  
Scratched  
Over 25mm Thru Paint



13: Qtr Panel nsr  
Dented  
With Paint Damage



14: Wheel nsr  
Corroded  
Light



15: Bumper Rear  
Scratched  
Over 100mm Thru Paint



16: Tailgate  
Scratched  
UpTo 25mm Thru Paint




17: Other  
N/A  
N/A



18: Wheel osr  
Corroded  
Light



19: Qtr Panel osr  
Rusted  
Holed



20: Door osr  
Scratched  
Over 25mm Thru Paint



21: Door osr  
Rusted  
Over 5mm




22: Sill os  
Rusted  
Over 5mm



23: Wheel osf  
Corroded  
Light



24: Door osf  
Scratched  
Over 25mm Thru Paint



25: Roof  
Rusted  
Over 5mm



26: Door nsr  
Rusted  
Over 5mm



27: Tailgate  
Rusted  
Over 5mm

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	Fault
		Steering	OK