



# VEHICLE INSPECTION REPORT

**GV67PUF**

## Suzuki Sx4 S-Cross 1.4 Boosterjet SZ5 ALLGRIP 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**5**

### Details

Reg. date	10/02/2018	Body Style	Hatchback	Last service miles	81,288
Year	2018	Keys	2	MOT Due	06/04/2027
Mileage	84,762 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	9	Doors	5
VIN	TSMJYBA2S00540169	Last service date	12/02/2026		

Last service 12/02/2026 at 81,288 miles- 9 services

### Tyres


NSF	FALKEN	5.0mm
NSR	SUNNY	5.0mm
OSF	FALKEN	5.0mm
OSR	SUNNY	5.0mm
Spare		

### Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

### Photos






## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Scuffed  
Over 25mm



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Scratched  
Over 100mm Thru Paint




4: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



5: Wing nsf  
Scratched  
Up To 25mm Thru Paint



6: Wheel nsf  
Scratched  
Up To 50mm



7: Door nsf  
Dented  
Over 30mm



8: Door Moulding nsf  
Scuffed (Unpainted)  
Over 100mm



9: Door nsr  
Dented  
With Paint Damage




10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Dented  
With Paint Damage



12: Bumper Rear  
Dented  
With Paint Damage



13: Tailgate  
Dented  
Over 30mm



14: Bumper Rear Moulding  
Scuffed (Unpainted)  
Over 100mm



15: Qtr Panel osr  
Dented  
With Paint Damage



16: Qtr Panel Arch Extension os  
Scuffed (Unpainted)  
Over 100mm



17: Door osr  
Dented  
With Paint Damage



18: Wheel osr  
Scratched  
Over 50mm



19: Door osf  
Dented  
Over 30mm



20: Door osf  
Scratched  
UpTo 25mm Thru Paint



21: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



22: Wheel osf  
Scratched  
Over 50mm



23: Wing osf  
Scratched  
Over 25mm Thru Paint



24: A Post os  
Chipped  
1 To 5



25: Roof  
Chipped  
1 To 5

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		