



VEHICLE INSPECTION REPORT

LB18SYR

Peugeot 208 1.6 THP GTi Prestige 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	31/08/2018	Body Style	Hatchback	MOT Due	27/07/2026
Year	2018	Service history	Yes	Gearbox	MANUAL
Mileage	72,596 Miles Warranted	Service documents	Printout	Gears	6
Fuel Type	Petrol	Number of stamps	1	Doors	3
Colour	RED	Last service date	10/08/2021		
VIN	VF3CA5GRMJW063564	Last service miles	25,579		

Last service 10/08/2021 at 25,579 miles- 1 main dealer service

Tyres



NSF	WESTLAKE	6.0mm
NSR	MATADOR	2.0mm
OSF	WESTLAKE	6.0mm
OSR	MATADOR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Front fog lights
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Manual sunroof
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Alarm
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Metallic Paint
- Passenger airbag
- Remote central locking
- PAS
- Trip computer
- Fixed panoramic glass roof
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Traction control
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Bumper Front Moulding
Missing
Replace



4: Wing nsf
Dented
Over 30mm



5: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Flasher Side Repeater ns
Broken
Replace



8: Door nsf
Dented
With Paint Damage



9: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



15: Aerial
Missing
Replace



16: Wheel osr
Scratched
Over 50mm



17: Qtr Panel osr
Dented
Between 10mm + 30mm



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Door osf
Dented
With Paint Damage



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		