



VEHICLE INSPECTION REPORT

LD65MLY

Ford C-Max 1.5 TDCi Titanium X 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	21/10/2015	VIN	WF0VXXGCEVFJ76282	Number of stamps	8
Year	2015	Body Style	MPV	Last service date	29/07/2025
Mileage	124,036 Miles Warranted	Keys	2	MOT Due	20/10/2026
Fuel Type	Diesel	Service history	Yes	Gearbox	MANUAL
Colour	BLACK	Service documents	Service Book	Gears	6

Last Service - 29.07.2025 at Unknown miles (8 services) Noisy driveshaft
 Gearbox faulty
 Noisy / juddering while driving

Tyres

NSF	RAPID	6.0mm
NSR	BUDGET	5.0mm
OSF	RAPID	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Up To 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Tailgate
Scratched
Rusted



11: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
UpTo 25mm Thru Paint



15: Wheel of
Scratched
Over 50mm



16: Wing of
Scratched
Up To 25mm Thru Paint



17: Screen Front
Chipped
Up To 10mm



18: Fascia Trim
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK