



# VEHICLE INSPECTION REPORT

**YV19TOJ**

## Kia Sportage 1.6 CRDi ISG GT-Line 5dr

nama  
 GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

### Details

Reg. date	30/06/2019	Body Style	Estate	Last service miles	66,297
Year	2019	Keys	2	MOT Due	29/06/2026
Mileage	74,929 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	3		
VIN	U5YPK812LKL708531	Last service date	25/06/2025		

£100 ADDITIONAL FEE

NO V5

Last service 25/06/2025 at 66,297 miles- 3 services. Book and print

Clutch replaced 19/12/2024 at 60,902 miles

### Tyres

NSF	HABILEAD	2.0mm
NSR	BUDGET	7.0mm
OSF	BUDGET	4.0mm
OSR	GENERAL TIRE	3.0mm


Spare

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front head restraints
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Alarm
- Front parking sensor
- PAS
- Trip computer
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Rear headrests
- 3x3 point rear seat belts
- Lane departure warning
- Remote central locking
- Heated front seat
- Rear parking sensor
- Radio/CD
- Roof rails
- Front armrest
- Lumbar support
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Dented  
With Paint Damage



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



10: Tailgate  
Scratched  
Over 25mm Thru Paint



11: Wheel osr  
Scratched  
Over 50mm



12: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



13: Door osr  
Dented  
With Paint Damage



14: Door osf  
Scratched  
Over 25mm Thru Paint



15: Wing osf  
 Scratched  
 Over 25mm Thru Paint



16: Wheel osf  
 Scratched  
 Over 50mm



17: Roof  
 Scratched  
 Over 25mm Thru Paint

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK