



VEHICLE INSPECTION REPORT

HV14GZT

Mazda CX-5 2.2d [175] Sport Nav 5dr AWD

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/03/2014	Body Style	Estate	Last service miles	110,895
Year	2014	Keys	2	MOT Due	22/03/2027
Mileage	111,687 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Electronic / Online	Gears	6
Colour	RED	Number of stamps	9		
VIN	JMZKEN92600165643	Last service date	11/03/2026		

£100 ADDITIONAL FEE.

LAST SERVICE 11/03/2026 @ 110,895 MILES (9 SERVICES, CONFIRMED BY BLUE ANCHOR GARAGE)
 Tyre pressure increase pressure message displayed

Tyres


NSF	PIRELLI	6.0mm
NSR	GOODYEAR	5.0mm
OSF	PIRELLI	6.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



4: Door nsf
Chipped
Edge Chip



5: Bumper Rear
Scratched
Up To 25mm Thru Paint



6: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



7: Qtr Panel osr
Poor Previous Repair
Poor Paint



8: B Post os
Poor Previous Repair
Poor Paint



9: Door osr
Poor Previous Repair
Poor Paint



10: Door osf
Scratched
Over 25mm Thru Paint



11: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



12: Wing osf
Scratched
Over 25mm Thru Paint



13: Wheel osf
Scratched
Over 50mm



14: Tailgate
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK