



VEHICLE INSPECTION REPORT

FY18NOF

Ford Fiesta 1.0 EcoBoost 140 ST-Line X 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	14/04/2018	VIN	WF0FXXGAHFJS32385	Gearbox	MANUAL
Year	2018	Body Style	Hatchback	Gears	6
Mileage	88,178 Miles Warranted	Keys	2	Doors	3
Fuel Type	Petrol	Service history	None		
Colour	GREY	MOT Due	11/05/2027		

NO SERVICE HISTORY Eml light is on
 Car been plugged in and detected
 Turbo/super charger under boost
 Catalyst system efficiency below threshold (bank 1)
 Roof cover in wrap
 O2 sensor signal biased/ stuck rich-bank 1 sensor 1

Tyres

NSF	SUNNY	4.0mm
NSR	ROYALBLACK	2.0mm
OSF	SUNNY	4.0mm
OSR	ROYALBLACK	3.0mm



Spare

Features


- Bluetooth connection
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsr
Scratched
Over 50mm



4: Wing nsf
Dented
With Paint Damage



5: Door nsr
Dented
With Paint Damage



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Dented
Between 10mm + 30mm



8: Qtr Panel nsr
Chipped
1 To 5



9: Tailgate
Dented
Over 30mm



10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Wheel osr
Scratched
Over 50mm



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osf
Scratched
Up To 25mm Thru Paint



14: Door osf
Dented
Between 10mm + 30mm



15: Wheel osf
Scratched
Over 50mm



16: Wing nsf
Poor Previous Repair
Poor Paint



17: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK