



# VEHICLE INSPECTION REPORT

**MK64YAV**

## Ford Focus 1.6 TDCi 115 Zetec Navigator 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	30/09/2014	Body Style	Hatchback	Last service miles	45,975
Year	2014	Keys	2	MOT Due	Expired
Mileage	77,514 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	4	Doors	5
VIN	WF0KXXGCBKEM50708	Last service date	21/05/2020		

£100 ADDITIONAL FEE

last service 21/5/20 @ 45,975 miles (4 services)

MOT EXPIRED - transported off site

### Tyres


NSF	SAILUN	5.0mm
NSR	SAILUN	5.0mm
OSF	SAILUN	5.0mm
OSR	SAILUN	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Poor Previous Repair  
Poor Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Screen Front  
Cracked  
Replace



6: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



7: Flasher Side Repeater ns  
Broken  
Replace



8: Door nsf  
Scratched  
UpTo 25mm Thru Paint



9: Door nsr  
Dented  
With Paint Damage



10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Dented  
Over 30mm



12: Bumper Rear  
Poor Previous Repair  
Poor Paint



13: Wheel osr  
Scratched  
Up To 50mm



14: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



15: Door osr  
Chipped  
1 To 5



16: Door osf  
Scratched  
UpTo 25mm Thru Paint



17: Wing osf  
Chipped  
1 To 5



18: Wheel osf  
Scratched  
Over 50mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK